

## N

Orlando Infiniti 4237 Millenia Blvd. Orlando, FL 32839

## **INVOICE - CUSTOMER COP**

This form is an itemized list of repairs and is part of the original Repair Order. This Repair Order Continuation is subject to all of the terms and conditions of the original Repair Order.

Page 1 Continued on next page

O1 CUSTOMER STATES OIL AND FILTER CHANGE AND TIRE ROTATION COMPLETED

Add-On? Tech Labor No ITW 401 No Charge Dealer

Every 5k or 6 Months-T0005 No.

Includes:Inspect battery condition-C0005

ENGINE OIL CHANGE SERVICE-U0400

Replace drain plug gasket-U0700

Insp All Fluid Levels-U0705

Check condition of wipers-W0031

Check Drive Belts-W0032

Check radiator hoses-W0033

Wash Exterior/vacuum mats-W0034

Tire Rotation-W0043

Tire Rotation-W0043

02 CUSTOMER STATES PERFORM RECALL COMPLETED

Add-On? Tech Labor 29.70 ITB14-015 OCS REPROGRAM-R1404 ITW 401 No Factory

O3 CUSTOMER STATES THERE IS A RATTLE FROM DRIVERS DOOR WHILE DRIVING THAT GOES AWAY WHEN YOU OPEN THE WINDOW A CRAC ISOLATED NOISE FROM LEADING UPPER CORNER OF DOOR PANEL WITH DTS. REMOVED PANEL, INSULATED DOOR FRAME AND PANEL, REFESTED Add-On? Tec 1

GENERAL REPAIRS-GENRP

No ITWAO1

Labor Factory

04 CUSTOMER STATES THE VEHICLE IS PULSATING WHILE BRAKING. STARTED HAPPENING AROUND 6500 MILES FOUND EXCESSIVE RUNOUT OF FRONT ROTORS RESURFACED FRONT ROTORS AND TESTED

Add-On? Teca Labor GENERAL REPAIRS-GENRP ITW 401 222.74 Factory No

05 CUSTOMER STATES THERE IS A CREAKING NOISE FROM THE STEERING COLUMN WHILE BEING TURNED.
TESTED WITH DTS IN HOT AND COOL CONDITIONS, VARIFIED CONCERN REALIGNED AND INSULATED COVERS, TESTED UNDER SAME CONDITIONS Add-On? Tecinology (Construction) Add-On? Tecinology (Construction) No ITW-01

Labor 504.87 Factory

Page 1 Continued on next page

Miscellaneous Shop Supplies and H. zardous Waste Removal Charge: 11% of the labor charge to a maximum of \$99 is included in supplies used on yo ir vehicle. This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop sup, lies or waste disposal, FS403.718 mandates a \$1.00 fee for each new tire sold in the State of Florida. FS403.7135 mandates a \$1.50 fee for each new or remanufactured battery sold in the Original Estimate Total Revised Estimate

I acknowledge notice and oral approval of an increase in the original estimated price

I acknowledge receipt of the parts and/or labor listed above. I have read reverse side for important and additional terms and conditions.

CUSTOMER SIGNATURE x

© 2001 Regan Consulting

CUSTOMER SIGNATURE X